2015 Mercedes-Benz Sprinter 3500

Headlight Information





H7 Bulb is plugged into a mounting assembly. Replace mounting mounting assembly and bulb by accessing the rear of the headlight assembly from inside the motor compartment.





