

IMPORTANT ALERT!

ATWOOD COUPLER INCOMPATIBILITY

The Atwood 88000 series coupler is currently incompatible with the Andersen 'No Sway' Weight Distribution Hitch.

This potential issue **ONLY** affects the **Atwood 88000 series** (stamped on the coupler as "Atwood model 88xxx" - xxx being any digits). **All other Atwood couplers work fine.** The similarly designed Marvel coupler also works just fine with the Andersen Weight Distribution Hitch.

Because of the particular design of the Atwood 88000 series coupler, when it is combined with the Andersen 'No Sway' Weight Distribution system there is a potential issue in which some couplers can become unlatched over time (due to wear from the internal latch system).

The ONLY solution we endorse at this time is to replace the 88xxx coupler.

Any coupler *other* than the Atwood 88xxx series will work fine.

Please feel free to contact us further if you have any concerns or questions.




Andersen Hitches ...Made in America!
Off: 208.523.6460 | Fax: 208.523.6562
www.andersenhitches.com
info@anderseninc.com

NEW FEATURE FOR ANDERSEN WEIGHT DISTRIBUTION HITCH

All current shipping Weight Distribution Hitches now features a permanent split ring that replaces the collar they previously shipped with.

The new split ring simply makes it more convenient to the end user who no longer needs to keep track of a collar for when they want to tow without weight distribution.



NEW MODEL

In the current WD Hitch the split ring (above) is permanently attached to the ball allowing you to pull a trailer without weight distribution.

PREVIOUS MODEL

In the previous model of the Weight Distribution Hitch the end user would attach this separate collar to allow towing without the weight distribution.

The collar is no longer needed.