

IMPORTANT ALERT!

ATWOOD COUPLER INCOMPATIBILITY

The Atwood 88000 series coupler is currently incompatible with the Andersen 'No Sway' Weight Distribution Hitch.

This potential issue **ONLY** affects the **Atwood 88000 series** (stamped on the coupler as "Atwood model 88xxx" - xxx being any digits). **All other Atwood couplers work fine.** The similarly designed Marvel coupler also works just fine with the Andersen Weight Distribution Hitch.

Because of the particular design of the Atwood 88000 series coupler, when it is combined with the Andersen 'No Sway' Weight Distribution system there is a potential issue in which some couplers can become unlatched over time (due to wear from the internal latch system).

The ONLY solution we endorse at this time is to replace the 88xxx coupler.

Any coupler *other* than the Atwood 88xxx series will work fine.

Please feel free to contact us further if you have any concerns or questions.



Andersen Hitches ...Made in America!
Off: 208.523.6460 | Fax: 208.523.6562
www.andersenhitches.com
info@anderseninc.com