



Several automakers expand their recalls to include cars equipped with defective driver-side air bag inflators

February 12, 2016: BMW, Daimler Vans (including Sprinter Vans labeled Mercedes-Benz, Dodge and Freightliner), Ford, Honda (including Acura), Mazda, Mercedes-Benz (including Chrysler), and Volkswagen (including Audi) have expanded their Takata recalls to include vehicles equipped with driver-side air bag inflators that Takata has declared defective. NHTSA alerted consumers that these expansions were imminent on Jan. 22.

An updated list of all makes, models and model years affected by Takata recalls is [available here](#). Ford and BMW has made Vehicle Identification Numbers searchable through NHTSA's [VIN lookup tool](#) so owners can enter their VIN and see if their vehicle is under recall. Honda, Volkswagen, and Mercedes-Benz will make affected VINs searchable in the coming days, and NHTSA will update its [Takata recall microsite](#) as those VINs become available.

If you want to receive up-to-the-minute email notifications only when there is new information on the Takata recall microsite, you can [subscribe for an alert](#).

subscriptions at any time on your [Subscriber Preferences Page](#). You will need to use your e-mail address to log in. If you have questions or problems with the subscription service, please contact subscriberhelp.govdelivery.com. This service is provided to you at no charge by [NHTSA](#).

This service is provided to you ellen@ekrus.org at no charge by National Highway Traffic Safety Administration (NHTSA) · 1200 New Jersey Avenue, SE · Washington, DC 20590 · 888-327-4236

