


### 3200 BHT Slide out room issues



Black Trim overlapping wall.

Streak of water running down



End of sealant  
tape

Water collects and seeps  
Under.

No tape and exposed  
screws.

